



General Order Number: 02-29	Effective Date: January 2010
Division: Apparatus and Equipment	
Chapter: Re-Torquing U-Bolts After Spring Work	
By Order of the Fire Chief: Marc S. Bashoor	Revision Date: N/A

POLICY

This General Order shall set forth a policy governing the required action to be taken following the performance of spring work.

DEFINITIONS

N/A

PROCEDURES / RESPONSIBILITIES

1. General Guideline

New U-bolts have a tendency to stretch, which either causes the spring to break or the center bolt to shear, if they are not re-torqued within seven (7) days.

Apparatus that has been in the shop for spring work must be returned to the vendor that performed the spring work within seven (7) days to have the U-bolts re-torqued.

REFERENCES

N/A

FORMS / ATTACHMENTS

N/A