

P-0117 - Depressed compression joint



P-0117 - Corrosion on beams



P-0117 - Cracks in approach pavement



P-0117 - Loose anchor bolt



P-0117 - Settlement of sidewalk



P-0169 - Corrosion on bearing



P-0169 - Missing compression seal



P-0169 - Corrosion on bearing



P-0169 - Detached compression seal



P-0185 - Potholes in the approach pavement



P-0185 - Corrosion at beam end



P-0185 - Spall and hole in sidewalk



P-0185 - Spall in the abutment



P-0190 - Delamination on beam

P-0190 - Cracks in compression seal



P-0190 - Section loss at beam end



P-0198E - Depressed compression seal



P-0198E - Corrosion below roadway joint



P-0198E - Detached compression seal



P-0198E - Corrosion on bearing



P-0198W - Delamination on beam end



P-0198W - Delamination on bearing



P-0198W - Delamination on beam



P-0204 - Section loss at beam end



P-0204 - Bulging compression seal



P-0204 - Section loss on beam
bottom flange



P-0204 - Spall and undermining
of sidewalk



P-0205 - Delamination on beam

P-0205 - Missing paint and corrosion on piles



P-0205 - Peeling paint on beams

P-0220 - Peeling paint on railing



P-0220 - Corrosion on beams



P-0220 - Spalls and cracks in the soffit



P-0220 - Delamination on beams



P-0220 - Rotated beam end



P-0273 - Tears on compression seal



P-0273 - Corrosion on beam end



P-0273 - Corrosion on bearing



P-0273 - Delamination at bearing



P-0283 - Missing anchor bolt



P-0283 - Corrosion at end of beam



P-0283 - Delamination on bearing

P-0294 - Corrosion on bearing



P-0294 - Corrosion on bearing



P-0294 - Cracks in masonry of pier nose



P-0294 - Spall in pier cap



P-0294 - Spalls and cracks in abutment



P-0396 - Depressed compression seal



P-0396 - Cracks and potholes in the approach pavement



P-0396 - Corrosion on beam



P-0396 - Missing anchor bolt



P-0484 - Tears on compression seal



P-0484 - Delamination on bearing



P-0484 - Delamination at beam end



P-0484 - Delamination at beam end



P-0490 - Tears on compression seal



P-0490 - Delamination on bearing



P-0490 - Potholes in the approach pavement



P-0490 - Section loss on pile

P-0579 - Corrosion on bearing



P-0579 - Corrosion on bearing



P-0579 - Cracks in the approach pavement



P-0579 - Potholes at the bridge transition



P-0579 - Settlement at the approach transition



P-0596 - Tears in compression seal



P-0596 - Corrosion at end of beam



P-0596 - Corrosion on bearing